

## SERVICE BULLETIN NO. MSB1078-142/2

### I. TECHNICAL DETAILS

#### 1.1 Category:

Mandatory

#### 1.2 Aircraft affected:

G 115           all S/N  
G 115A         all S/N

#### 1.3 Time of Compliance:

Item 1.8.1:     Immediately after receipt of this Service Bulletin

#### 1.4 Subject:

ATA - Code:    N/A  
                  Revision of the aircraft documentation. Information about revision status.

#### 1.5 Reason:

This Service Bulletin informs about the current revision status of the Flight Manual / Maintenance Manual / Illustrated Parts Catalogue of the GROB G 115, G115A models. Future documentation changes will be published under MSB 1078-142, followed by /sequence number.

#### 1.6 Concurrent documents:

N/A

#### 1.7 Approval Note:

The technical information contained in this document has been approved under the authority of EASA Design Organisation Approval No. EASA.21J.030.

G 115  
G 115A

### **1.8 Accomplishment/ Instructions**

1.8.1 Check aircraft documentation for correct issue and revision status in accordance with the list below:

<b>G115, G115A</b>	<b>Deutsche Ausgabe</b>	<b>English Issue</b>
<b>Flughandbuch Flight Manual</b>	Ausgabe 2, Revision 3, 29. April 1997 Ausgabe 2, Revision 2, Dezember 1995 (ohne TM 1078-68)	Issue 2, Revision 3, 29. April 1997 Issue 2, Revision 2, December 1995 (without SB 1078-68)
<b>Wartungshandbuch Maintenance Manual</b>	Ausgabe 1, Revision 5, Januar 2000	Issue 1, Revision 5, January 2000
<b>Ersatzteilkatalog Illustrated Parts Catalogue</b>	Ausgabe 2, Revision 1, Dezember 2006	Issue 2, Revision 1, December 2006

**Note: Revision 3 to the Flight Manual G115/G115A resulted from Service Bulletin 1078-68, optional "Modification of the Flap Control". Depending on incorporation of SB 1078-68, either revision 2 or revision 3 of the Flight Manual is possible. To eliminate this ambiguity, the next revision of the Flight Manual G115/G115A will bring the Flight Manual to a common revision standard, regardless of aircraft modification standard.**

### **1.9 Repetitive Actions**

N/A

### **1.10 Mass (Weight) and CG:**

N/A

## **II. PLANNING INFORMATION**

### **2.1 Material & Availability:**

All necessary revision pages for the affected manuals may be requested from GROB Product Support.

G 115  
G 115A

**2.2 Special Tools:**

N/A

**2.3 Labour costs:**

approx. 0,1 hour

**2.4 Reference documents:**

see table above

**2.5 Credit:**

N/A

**III. REMARKS**

- 3.1** The exchange of the documentation may be performed by a qualified person / an authorised aviation workshop and has to be logged in the documentation Record of Revision Page(s).
- 3.2** If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us.
- 3.3** For questions and assistance please contact:

Michael Reinhold, Customer Service  
phone: +49 8268 998 105  
fax: +49 8268 998 200  
e-mail: [productsupport@grob-aerospace.de](mailto:productsupport@grob-aerospace.de)

G 115  
G 115A