

SERVICE BULLETIN NO. MSB1078-143/2

I. TECHNICAL DETAILS

1.1 Category:

Mandatory

1.2 Aircraft affected:

G 115B all S/N

1.3 Time of Compliance:

Item 1.8.1: Immediately after receipt of this Service Bulletin

1.4 Subject:

ATA - Code: N/A
Revision of the aircraft documentation. Information about revision status.

1.5 Reason:

This Service Bulletin informs about the current revision status of the Flight Manual / Maintenance Manual / Illustrated Parts Catalogue of the GROB G 115B model. Future documentation changes will be published under MSB 1078-143, followed by /sequence number.

1.6 Concurrent documents:

N/A

1.7 Approval Note:

The technical information contained in this document has been approved under the authority of EASA Design Organisation Approval No. EASA.21J.030.

G 115B

1.8 Accomplishment/ Instructions

1.8.1 Check aircraft documentation for correct issue and revision status in accordance with the list below:

G 115B	Deutsche Ausgabe	English Issue
Flughandbuch Flight Manual	Ausgabe 1, Revision 1 29. April 1997	Issue 1, Revision 2, 29. April 1997
	Ausgabe 1, August 1992 (ohne TM 1078-68)	Issue 1, Revision 1, 14. May 1993 (without SB 1078-68)
Wartungshandbuch Maintenance Manual	Ausgabe 1, Revision 2, 31. Januar 2000	Issue 1, Revision 2, 31. January 2000
Ersatzteilkatalog Illustrated Parts Catalogue	Ausgabe 2, Revision 1, Dezember 2006	Issue 2, Revision 1, December 2006

Note: Revision 1 (German Issue) or revision 2 (English Issue) to the Flight Manual G115B resulted from Service Bulletin 1078-68, optional "Modification of the Flap Control". Depending on incorporation of SB 1078-68, either the a.m. revision status or the previous revision status of the Flight Manual is possible. To eliminate this ambiguity, the next revision of the Flight Manual G115B will bring the Flight Manual to a common revision standard, regardless of aircraft modification standard.

1.9 Repetitive Actions

N/A

1.10 Mass (Weight) and CG:

N/A

II. PLANNING INFORMATION

2.1 Material & Availability:

All necessary revision pages for the affected manuals may be requested from GROB Product Support.

2.2 Special Tools:

N/A

2.3 Labour costs:

approx. 0,1 hour

2.4 Reference documents:

see table above

2.5 Credit:

N/A

III. REMARKS

- 3.1** The exchange of the documentation may be performed by a qualified person / an authorised aviation workshop and has to be logged in the documentation Record of Revision Page(s).
- 3.2** If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us.
- 3.3** For questions and assistance please contact:

Michael Reinhold, Customer Service
phone: +49 8268 998 105
fax: +49 8268 998 200
e-mail: productsupport@grob-aerospace.de