


Doc. No.: GROB.TM.001		Grob Aircraft AG									
Chapter: 2											
Type:	all GROB	Service Bulletins (issued / in preparation)							29 October 2009		
LBA-TCDS No.:	all GROB										
SB-No.	ÄM No.	Subject	Date of issue	TCDS 306	TCDS 315	TCDS 320	TCDS 817	TCDS 869	TCDS 1078	TCDS 1121	Remarks
MSB-GROB-001											
MSB1121-002	N/A	Mode-S Transponder Mode- S Transponder									in preparation
OSB1121-003	N/A	Überprüfung des Wasserballast Anschlusses Inspection of the water ballast connection	29. Okt 09	X	X	X					

SB are listed according to number, not date of issue
X = applicable N/A = not applicable P = installation during production